

PU SHOP SHIFT REPORT

Date: October 26, 2025

Production Summary

Sr.	Model	Part Name	Part Code	PU-1			PU-2			PU-3			PU-4			Total Qty
				S-A	S-B	S-C	S-A	S-B	S-C	S-A	S-B	S-C	S-A	S-B	S-C	
1	YTA/YTB	FSB-L AIR BAG	TTN112800	0	0	0	0	0	0	885	1,149	0	0	0	0	2,034
2	YTA/YTB	FSB-R AIR BAG	TTN212810	0	0	0	0	0	0	883	1,154	0	0	0	0	2,037
3	YTA/YTB	FR CUSH NORMAL	TTN322810	587	345	0	0	0	0	412	417	0	0	0	0	1,761
4	YTA/YTB	FR CUSH SBR	TTN322820	587	552	0	0	0	0	410	421	0	0	0	0	1,970
5	YTA	RR BACK-40% EXP.	TTN412820	0	0	0	512	309	0	0	0	0	0	0	0	821
6	YTA	RR BACK-60% EXP.	TTN512810	0	0	0	512	309	0	0	0	0	0	0	0	821
7	YTA	RR CUSH	TTN422800	529	503	0	0	0	0	0	0	0	0	0	0	1,032
8	YED HB	FSB LH	YEN112810	0	0	0	508	397	0	0	0	0	0	0	0	905
9	YED HB	FSB RH	YEN212810	0	0	0	519	322	0	0	0	0	0	0	0	841
10	YED HB	FSC NORMAL	YEN322800	0	0	0	515	387	0	0	0	0	0	0	0	902
11	YED HB	FSC SBR	YEN322810	0	0	0	525	409	0	0	0	0	0	0	0	934
12	YED HB	RSB 100%	YEN412800	0	0	0	315	339	0	0	0	0	0	0	0	654
13	YED HB	RSB 60%	YEN512800	0	0	0	0	0	0	97	100	0	0	0	0	197
14	YED HB	RSB 40%	YEN412810	0	0	0	0	0	0	97	100	0	0	0	0	197
15	YED HB	RSC	YEN422800	483	284	0	0	0	0	0	0	0	0	0	0	767
16	YTB J00	FSB LH	YTN112800	0	0	0	0	0	0	45	49	0	0	0	0	94
17	YTB J00	FSB RH	YTN212800	0	0	0	0	0	0	50	47	0	0	0	0	97
18	YTB J00	FSC NRM	YTN222810	0	0	0	0	0	0	45	49	0	0	0	0	94
19	YTB J00	FSC SBR	YTN122810	0	0	0	0	0	0	50	47	0	0	0	0	97
20	YY8	REAR SEAT CUSHION 10R (40%)	Y8N422800	0	0	0	0	0	0	68	74	0	0	0	0	142
21	YY8	REAR SEAT CUSHION 10L (60%)	Y8N522800	0	0	0	0	0	0	68	74	0	0	0	0	142
22	YY8	REAR SEAT BACK 10R	Y8N412810	0	0	0	0	0	0	70	63	0	0	0	0	133
23	YY8	REAR SEAT BACK 10L	Y8N512840	0	0	0	0	0	0	70	63	0	0	0	0	133
TOTALS				2,186	1,684	0	3,406	2,472	0	3,250	3,807	0	0	0	0	16,805

PU SHOP SHIFT REPORT

Date: October 26, 2025

Breakdown Log

Sr.No	Date	PU Plant	Shift	Breakdown Details	Breakdown Time
No Breakdown					

Prepared By

Checked By

Approved By